

# COIL REPLACEMENT

## MCW/TTK (HI-WALL) Series

Series	Model no.	P/N	Listed Price
GENIO II	MCW5099B5A0	PP222372	5,000
	MCW5099B5B0	PP222372	5,000
	MCW5129B5A0	PP222802	6,500
	MCW5129B5B0	PP222801	6,500
	MCW5129B5C0	PP222802	6,500
	MCW5189B5A0	PP222801	6,500
	MCW5189B5B0	PP222801	6,500
	MCW5249B0A0	PP222542	7,500
	MCW5249B0B0	PP222542	7,500
TRIPPLE E	MCW509DB5A01	70-COIL0008 (11100050315)	6,000
	MCW512DB5A01	1213090105	7,000
	MCW512DB5A11	1110051119	7,000
	MCW518DB5A01	1110050926	8,000
	MCW524DB0A01	70-COIL0003 (11100050926)	9,000
PREMIO	MCW509SB5A00	201532390123	6,000
	MCW512SB5A00	201532700009	7,000
	MCW518SB5A00	70-COIL0002 (20153309006)	7,500
	MCW524SB0A00	70-COIL0006 (20153309009)	9,000
	MCW524SB5A00	70-COIL0006 (20153309009)	9,000
	MCW530SB0A00	201533190009	9,000
	TTK509SB5E00	201537590064	6,000
	TTK512SB5E00	201537790029	6,500
	TTK515SB5E00	201537890007	8,000
	TTK518SB5E00	201537890007	8,000
PRESTIGE	MCW5097B5A00	05-4610-0000023A	5,000
	MCW5127B5A00	05-4613-0000027A	6,000
	MCW5187B5A00	05-4618-0000021A	8,000
	MCW5247B5A00	05-4618-0000021A	8,000
	TTK5097B5E00	05-0210-5021061	6,000
	TTK5127B5E00	05-0213-5021335	8,000
	TTK5187B5E00	05-0213-5021335	8,000
	TTK5247B5E00	05-0126-0000032	10,000
30,000BTU	MCW5306BA00	D30-1	9,000
36,000BTU	MCW5366BA00	DD080001CA	10,000
BRAVO	MCW509BB5A00	70-COIL0020	5,000
	MCW512BB5A00	0100256505	5,500
	MCW512BB5A01	0100256501	5,500
	MCW515BB5A00	01002590	6,000
	MCW518BB5A00	0100257204	7,000
	MCW518BB5A01	01002575	7,000
	MCW524BB5A00	01002924	8,000
BRAVO INVERTER	MCWA09BB5A00	01002321	5,000
	MCWA12BB5A00	0100256502	5,500
	MCWA18BB5A00	01002575	6,000

# COIL REPLACEMENT

## MCX Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price	
12,000	MCX512CB0DAA	026-0560-005	3,000	30,000	MCX530CB0DAA	026-0563-005	8,000	
	MCX512CB0TAA	026-0560-005	3,000		MCX530CB0TAA	026-0563-005	8,000	
	MCX512E10RMA	026-0560-005	3,000		MCX530CB0WDB	026-0563-005	8,000	
	MCX512E10RNA	026-0560-005	3,000		MCX530E10RMA	026-0563-005	8,000	
	MCX512E10RPA	026-0560-005	3,000		MCX530E10RPA	026-2086	6,500	
	MCX512E10RQA	026-0560-005	3,000		MCX530E10WDB	026-0563-005	8,000	
	MCX512E10WDB	026-0560-005	3,000		MCX530E10WEA	026-0563-005	8,000	
	MCX512E10WEA	026-0560-005	3,000		MCX530E10WFA	026-2086	6,500	
	MCX512E10WFA-DM	026-0560-005	3,000		MCX530EB0DAA	026-0563-005	8,000	
	MCX512E1ERSA	026-0560-005	3,000		MCX530EB0DBA	026-2086	6,500	
	MCX512E1ERTA	026-0560-005	3,000		MCX530EB0RFB	026-0563-005	8,000	
	MCX512E1ERUA	026-0560-005	3,000		MCX530EB0RKA	026-0563-005	8,000	
	MCX512E1ERVA	026-0560-005	3,000		MCX530EB0RMA	026-0563-005	8,000	
	MCX512E1EWPA	026-0560-005	3,000		MCX530EB0RPA	026-2086	6,500	
	MCX512E1EWPB	026-0560-005	3,000		MCX530EB0RPB	026-2086	6,500	
	MCX512E1EWRA	026-0560-005	3,000		MCX530EB0TAA	026-0563-005	8,000	
	MCX512E1EWSA	026-0560-005	3,000		MCX530EB0TBA	026-2086	6,500	
	MCX512EB0DAA	026-0560-005	3,000		MCX530EB0WBB	026-0563-005	8,000	
		026-2131	3,000		MCX530EB0WBD	026-0563-005	8,000	
	MCX512EB0DBA	026-2131	3,000		MCX530EB0WEA	026-0563-005	8,000	
	MCX512EB0RKA	026-0560-005	3,000		MCX530EB0WFA	026-2086	6,500	
	MCX512EB0RLA	026-0560-005	3,000		MCX530EB5RBB	026-0564-006	10,000	
	MCX512EB0RMA	026-0560-005	3,000		MCX530EB5WBB	026-0564-006	10,000	
	MCX512EB0RNA	026-0560-005	3,000		MCX530EBHRSA	026-0563-005	8,000	
	MCX512EB0RPA	026-0560-005	3,000		MCX530G10RAA	026-2589	5,000	
	MCX512EB0RPB-DM	026-2131	3,000		MCX530G10RBA	026-2589	5,000	
	MCX512EB0RQA	026-0560-005	3,000		MCX530G10WAA	026-2589	5,000	
	MCX512EB0RQB	026-2131	3,000		MCX530G10WBA	026-2589	5,000	
	MCX512EB0TAA	026-0560-005	3,000		MCX530G1HRAA	026-2589	5,000	
	MCX512EB0TBA	026-2131	3,000		MCX530GB0RAA	026-2589	5,000	
	MCX512EB0WBB	026-0560-005	3,000		MCX530GB0TAA	026-2589	5,000	
	MCX512EB0WBD	026-0560-005	3,000		MCX530GB0WAA	026-2589	5,000	
	MCX512EB0WEA	026-0560-005	3,000		MCX530GB5RAA	026-2590	8,000	
	MCX512EB0WFA	026-0560-005	3,000		MCX530GB5WAA	026-2590	8,000	
	MCX512EB5RFB	026-2496	3,500		MCX530GBHRAA	026-2589	5,000	
	MCX512EB5RGB	026-2496	3,500		MCX530HB50AA	026-2959	11,000	
	MCX512EB5RGC	026-0561-007	3,500		36,000	MCX536CB0DAA	026-0564-005	9,000
	MCX512EB5WBB	026-0561-007	3,500			MCX536CB0TAA	026-0564-005	9,000
	MCX512EB5WCA	026-2496	3,500			MCX536CB0WDC	026-0564-005	9,000
	MCX512EBERSA	026-0560-005	3,000			MCX536CB0WDD	026-0564-005	9,000
	MCX512EBERTA	026-0560-005	3,000			MCX536E10RMA	026-0564-005	9,000
	MCX512EBERUA	026-0560-005	3,000			MCX536E10RPA	026-2087	9,000
MCX512EBERVA	026-0560-005	3,000	MCX536E10WDB	026-0564-005		9,000		
MCX512EBEWMA	026-0560-005	3,000	MCX536E10WEA	026-0564-005		9,000		
MCX512EBEWMB	026-0560-005	3,000	MCX536E10WFA	026-2087		9,000		
MCX512EBEWRA	026-0560-005	3,000	MCX536E1JRSA	026-0564-005		9,000		
MCX512EBEWSA	026-0560-005	3,000	MCX536E1JRUA	026-2087		9,000		

# COIL REPLACEMENT

## MCX Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
	MCX512E10WDB	026-0560-005	3,000		MCX536E1JWPA	026-0564-005	9,000
	MCX512EB0WBD	026-0560-005	3,000		MCX536E1JWPB	026-0564-005	9,000
	MCX512G10RAA	026-2683	3,500		MCX536E1JWRA	026-0564-005	9,000
	MCX512G10RBA	026-2819	3,500		MCX536E1JWSA	026-2087	9,000
	MCX512G10RCA	026-2819	3,500		MCX536EB0DAA	026-0564-005	9,000
	MCX512G10WAA	026-2683	3,500		MCX536EB0DBA	026-2087	9,000
	MCX512G10WBA	026-2819	3,500		MCX536EB0REB	026-0564-005	9,000
	MCX512G10WCA	026-2819	3,500		MCX536EB0RKA	026-0564-005	9,000
	MCX512G1ERAA	026-2819	3,500		MCX536EB0RMA	026-0564-005	9,000
	MCX512GB0RAA	026-2618	3,500		MCX536EB0RPA	026-2087	9,000
	MCX512GB0RBA	026-2687	3,500		MCX536EB0RPB	026-2087	9,000
	MCX512GB0RBA	026-2687	3,500		MCX536EB0TAA	026-0564-005	9,000
	MCX512GB0RCA	026-2853	3,500		MCX536EB0TBA	026-2087	9,000
	MCX512GB0TAA	026-2687	3,500		MCX536EB0WBB	026-0564-005	9,000
	MCX512GB0TBA	026-2853	3,500		MCX536EB0WBD	026-0564-005	9,000
	MCX512GB0WAA	026-2618	3,500		MCX536EB0WEA	026-0564-005	9,000
	MCX512GB0WBA	026-2687	3,500		MCX536EB0WFA	026-2087	9,000
	MCX512GB0WCA	026-2853	3,500		MCX536EB5WAA	026-2107	11,000
	MCX512GB5RAA	026-2618	3,500		MCX536EB5WCA	026-2573	13,500
	MCX512GB5WAA	026-2618	3,500		MCX536EBHWRA	026-0564-005	9,000
	MCX512GBERAA	026-2819	3,500		MCX536EBJRSA	026-0564-005	9,000
	MCX512HB50AA	026-2884	3,500		MCX536EBJRTA	026-2087	9,000
18,000	MCX518CB0DAA	026-2499	4,500		MCX536EBJWMA	026-0564-005	9,000
	MCX518CB0TAA	026-2499	4,500		MCX536EBJWMB	026-0564-005	9,000
	MCX518CB0WDB	026-2499	4,500		MCX536EBJWRA	026-0564-005	9,000
	MCX518CB0WDD	026-2499	4,500		MCX536E10WDB	026-0564-005	9,000
	MCX518E10RJB	026-2499	4,500		MCX536EB0WBD	026-0564-005	9,000
	MCX518E10RMA	026-2499	4,500		MCX536EBJWSA	026-2087	9,000
	MCX518E10RNA	026-2499	4,500		MCX536G10RAA	026-2828	8,000
	MCX518E10RPA	026-2499	4,500		MCX536G10RBA	026-2828	8,000
	MCX518E10RQA	026-2499	4,500		MCX536G10WAA	026-2828	8,000
	MCX518E10WDB	026-2499	4,500		MCX536G10WBA	026-2828	8,000
	MCX518E10WEA	026-2499	4,500		MCX536G1JRAA	026-2828	8,000
	MCX518E10WFA	026-2499	4,500		MCX536GB0RAA	026-2828	8,000
	MCX518E10WFA-DM	026-2499	4,500		MCX536GB0TAA	026-2828	8,000
	MCX518E1FRSA	026-2499	4,500		MCX536GB0WAA	026-2828	8,000
	MCX518E1FRTA	026-2499	4,500		MCX536GB5RAA	026-2580	9,000
	MCX518E1FRUA	026-2499	4,500		MCX536GB5RBA	026-2824	12,000
	MCX518E1FRVA	026-2499	4,500		MCX536GB5WAA	026-2580	9,000
	MCX518E1FWPA	026-2499	4,500		MCX536GB5WBA	026-2824	12,000
	MCX518E1FWPB	026-2499	4,500		MCX536GBJRAA	026-2828	8,000
	MCX518E1FWRA	026-2499	4,500		MCX536HB50AA	026-2960	11,000
	MCX518E1FWSA	026-2499	4,500	42,000	MCX042E10WAA	026-1708	6,500
	MCX518EB0DAA	026-2499	4,500		MCX042EB0WAA	026-1708	6,500
	MCX518EB0DBA	026-2495	4,500		MCX042E10RCA	026-2088	7,500
	MCX518EB0RKA	026-2499	4,500		MCX042E10WAA	026-1708	6,500
	MCX518EBORLA	026-2499	4,500		MCX042E10WBA	026-1708	6,500

# COIL REPLACEMENT

## MCX Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
	MCX518EB0RMA	026-2499	4,500		MCX042E10WCA	026-2088	7,500
	MCX518EB0RNA	026-2499	4,500		MCX042E1JRBA	026-1708	6,500
	MCX518EB0RPA	026-2499	4,500		MCX042E1JRCA	026-2088	7,500
	MCX518EB0RPB-DM	026-2495	4,500		MCX042E1JWAA	026-1708	6,500
	MCX518EB0RQA	026-2499	4,500		MCX042E1JWBA	026-1708	6,500
	MCX518EB0RQB	026-2495	4,500		MCX042E1JWCA	026-2088	7,500
	MCX518EB0TAA	026-2499	4,500		MCX042EB0DAA	026-1708	6,500
	MCX518EB0TBA	026-2495	4,500		MCX042EB0DBA	026-2088	7,500
	MCX518EB0WBB	026-2499	4,500		MCX042EB0RBA	026-1708	6,500
	MCX518EB0WBD	026-2499	4,500		MCX042EB0RCA	026-2088	7,500
	MCX518EB0WEA	026-2499	4,500		MCX042EB0RKA	026-1708	6,500
	MCX518EB0WFA	026-2499	4,500		MCX042EB0RPB	026-2088	7,500
	MCX518E10WDB	026-2499	4,500		MCX042EB0TAA	026-1708	6,500
	MCX518EB0WBD	026-2499	4,500		MCX042EB0TBA	026-2088	7,500
	MCX518EB5RFB	026-0562-005	5,500		MCX042EB0WAA	026-1708	6,500
	MCX518EB5RGB	026-1541	6,000		MCX042EB0WAB	026-1708	6,500
	MCX518EB5RGC	026-0562-005	5,500		MCX042EB0WBA	026-1708	6,500
	MCX518EB5RIA-DM	026-0562-007	7,000		MCX042EB0WCA	026-2088	7,500
	MCX518EB5WBB	026-0562-005	5,500		MCX042EB5WAA	026-2111	12,000
	MCX518EB5WBC	026-0562-005	5,500		MCX042EBJRBA	026-1708	6,500
	MCX518EB5WCA-DM	026-0562-007	7,000		MCX042EBJRCA	026-2088	7,500
	MCX518EBFRSA	026-2499	4,500		MCX042EBJWAA	026-1708	6,500
	MCX518EBFRTA	026-2499	4,500		MCX042EBJWAB	026-1708	6,500
	MCX518EBFRUA	026-2499	4,500		MCX042EBJWBA	026-1708	6,500
	MCX518EBFRVA	026-2499	4,500		MCX042E10RBA	026-1708	6,500
	MCX518EBFWMA	026-2499	4,500		MCX042EBJWCA	026-2088	7,500
	MCX518EBFWMB	026-2499	4,500		MCX042G10RAA	026-2592	6,000
	MCX518EBFWRA	026-2499	4,500		MCX042G10WAA	026-2592	6,000
	MCX518EBFWSA	026-2499	4,500		MCX042G1JRAA	026-2592	6,000
	MCX518G10RAA	026-2684	3,500		MCX042GB0RAA	026-2592	6,000
	MCX518G10RBA	026-2684	3,500		MCX042GB0TAA	026-2592	6,000
	MCX518G10WAA	026-2684	3,500		MCX042GB0WAA	026-2592	6,000
	MCX518G10WBA	026-2684	3,500		MCX042GB5RAA	026-2640	12,000
	MCX518G1FRAA	026-2684	3,500		MCX042GB5WAA	026-2640	12,000
	MCX518GB0RAA	026-2576	3,500		MCX042GBJRAA	026-2592	6,000
	MCX518GB0TAA	026-2576	3,500		MCX042HB50AA	026-2961	12,000
	MCX518GB0WAA	026-2576	3,500	48,000	MCX048E10RBA	026-1602	9,000
	MCX518GB5RAA	026-2577	4,100		MCX048E10RCA	026-2089	10,000
	MCX518GB5WAA	026-2577	4,100		MCX048E10WAA	026-1602	9,000
	MCX518GBFRAA	026-2684	3,500		MCX048E10WBA	026-1602	9,000
	MCX518HB50AA	026-2939	5,500		MCX048E10WCA	026-2089	10,000
24,000	MCX524CB0DAA	026-0562-005	5,500		MCX048E1KRBA	026-1602	9,000
	MCX524CB0TAA	026-0562-005	5,500		MCX048E1KRCA	026-2089	10,000
	MCX524CB0WEB	026-0562-005	5,500		MCX048E1KWAA	026-1602	9,000
	MCX524E10RMA	026-0562-005	5,500		MCX048E1KWBA	026-1602	9,000
	MCX524E10RNA	026-0562-005	5,500		MCX048E1KWCA	026-2089	10,000
	MCX524E10RPA	026-0562-005	5,500		MCX048EB0DAA	026-1602	9,000



# COIL REPLACEMENT

## MCX Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
	MCX524E10RQA	026-0562-005	5,500		MCX048EB0DBA	026-2133	8,000
	MCX524E10WDB	026-0562-005	5,500		MCX048EB0RBA	026-1602	9,000
	MCX524E10WEA	026-0562-005	5,500		MCX048EB0RCA	026-2089	10,000
	MCX524E10WFA	026-0562-005	5,500		MCX048EB0RKA	026-1602	9,000
	MCX524E1BRSA	026-0562-005	5,500		MCX048EB0RPB	026-2133	8,000
	MCX524E1BRTA	026-0562-005	5,500		MCX048EB0TAA	026-1602	9,000
	MCX524E1BRUA	026-0562-005	5,500		MCX048EB0TBA	026-2133	8,000
	MCX524E1BRVA	026-0562-005	5,500		MCX048EB0WAA	026-1602	9,000
	MCX524E1BWPA	026-0562-005	5,500		MCX048EB0WAB	026-1602	9,000
	MCX524E1BWPB	026-0562-005	5,500		MCX048EB0WBA	026-1602	9,000
	MCX524E1BWRA	026-0562-005	5,500		MCX048EB0WCA	026-2089	10,000
	MCX524E1BWSA	026-0562-005	5,500		MCX048EBKRBA	026-1602	9,000
	MCX524EB0DAA	026-0562-005	5,500		MCX048EBKRCA	026-2089	10,000
	MCX524EB0DBA	026-0562-005	5,500		MCX048EBKWAA	026-1602	9,000
	MCX524EB0RKA	026-0562-005	5,500		MCX048EBKWBA	026-1602	9,000
	MCX524EB0RLA	026-0562-005	5,500		MCX048EBKWCA	026-2089	10,000
	MCX524EB0RMA	026-0562-005	5,500		MCX048E10WAA	026-1602	9,000
	MCX524EB0RNA	026-0562-005	5,500		MCX048EB0WAA	026-1602	9,000
	MCX524EB0RPA	026-0562-005	5,500		MCX048G10RAA	026-2829	9,000
	MCX524EB0RPB-DM	026-0562-005	5,500		MCX048G10WAA	026-2829	9,000
	MCX524EB0RQA	026-0562-005	5,500		MCX048G1KRAA	026-2829	9,000
	MCX524EB0RQB	026-0562-005	5,500		MCX048GB0RAA	026-2582	7,000
	MCX524EB0TAA	026-0562-005	5,500		MCX048GB0TAA	026-2582	7,000
	MCX524EB0TBA	026-0562-005	5,500		MCX048GB0WAA	026-2582	7,000
	MCX524EB0WBB	026-0562-005	5,500		MCX048GBKRAA	026-2829	9,000
	MCX524EB0WDB	026-0562-005	5,500		MCX048HB00AA	026-2979	8,000
	MCX524EB0WEA	026-0562-005	5,500	60,000	MCX060E10RBA	026-1603	12,500
	MCX524EB0WFA	026-0562-005	5,500		MCX060E10RCA	026-2090	12,500
	MCX524E10WDB	026-0562-005	5,500		MCX060E10WAA	026-1603	12,500
	MCX524EB0WDB	026-0562-005	5,500		MCX060E10WBA	026-1603	12,500
	MCX524EB5RFB	026-1542	8,000		MCX060E10WCA	026-2090	12,500
	MCX524EB5RGB	026-1542	8,000		MCX060E1LRBA	026-1603	12,500
	MCX524EB5RHA	026-2565	9,000		MCX060E1LRCA	026-2090	12,500
	MCX524EB5WBB	026-1542	8,000		MCX060E1LWAA	026-1603	12,500
	MCX524EB5WCA	026-2565	9,000		MCX060E1LWBA	026-1603	12,500
	MCX524EBBRSA	026-0562-005	5,500		MCX060E1LWCA	026-2090	12,500
	MCX524EBBRTA	026-0562-005	5,500		MCX060EB0DAA	026-1603	12,500
	MCX524EBBRUA	026-0562-005	5,500		MCX060EB0DBA	026-2134	12,500
	MCX524EBBRVA	026-0562-005	5,500		MCX060EB0RBA	026-1603	12,500
	MCX524EBBWMA	026-0562-005	5,500		MCX060EB0RCA	026-2090	12,500
	MCX524EBBWMB	026-0562-005	5,500		MCX060EB0RKA	026-1603	12,500
	MCX524EBBWRA	026-0562-005	5,500		MCX060EB0RPB	026-2134	12,500
	MCX524EBBWSA	026-0562-005	5,500		MCX060EB0TAA	026-1603	12,500
	MCX524G10RAA	026-2688	5,500		MCX060EB0TBA	026-2134	12,500
	MCX524G10RBA	026-2820	4,500		MCX060EB0WAA	026-1603	12,500
	MCX524G10RCA	026-2820	4,500		MCX060EB0WAB	026-1603	12,500
	MCX524G10WAA	026-2688	5,500		MCX060EB0WBA	026-1603	12,500

# COIL REPLACEMENT

## MCX Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
	MCX524G10WBA	026-2820	4,500		MCX060EB0WCA	026-2090	12,500
	MCX524G10WCA	026-2820	4,500		MCX060EBLRBA	026-1603	12,500
	MCX524G1BRAA	026-2820	4,500		MCX060EBLRCA	026-2090	12,500
	MCX524GB0RAA	026-2587	5,500		MCX060EBLWAA	026-1603	12,500
	MCX524GB0RBA	026-2688	5,500		MCX060EBLWBA	026-1603	12,500
	MCX524GB0TAA	026-2688	5,500		MCX060EBLWCA	026-2090	12,500
	MCX524GB0WAA	026-2587	5,500		MCX060E10WAA	026-1603	12,500
	MCX524GB0WBA	026-2688	5,500		MCX060EB0WAA	026-1603	12,500
	MCX524GB5RAA	026-2586	6,500		MCX060G10RAA	026-2686	12,500
	MCX524GB5RBA	026-2682	6,500		MCX060G10WAA	026-2686	12,500
	MCX524GB5WAA	026-2586	6,500		MCX060G1LRAA	026-2686	12,500
	MCX524GB5WBA	026-2682	6,500		MCX060GB0RAA	026-2641	12,500
	MCX524GBBRAA	026-2820	4,500		MCX060GB0TAA	026-2641	12,500
	MCX524HB50AA	026-2940	7,500		MCX060GB0WAA	026-2641	12,500
					MCX060GBLRAA	026-2686	12,500
					MCX060HB00AA	026-2980	7,500

## MCD Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
9,000	MCD009AA50AA-LH	026-2866	3,000	60,000	MCD060BA00BA	026-0219	11,000
12,000	MCD012AA00BA-LH	026-0200	2,500		MCD060BAP0BA	026-0219	11,000
	MCD012AA00BA-RH	026-0200-001	2,500		MCD060D1P0AA	026-1606	7,000
	MCD012AA00CA-LH	026-0200	2,500		MCD060D1P0BA	026-1606	7,000
	MCD012AA00CA-RH	026-0200-001	2,500		MCD060D1P0CA	026-1606	7,000
	MCD012AA00DA-LH	026-2854	2,000		MCD060D1Z0AA	026-1606	7,000
	MCD012AA00DA-RH	026-2863	2,000		MCD060D1Z0BA	026-1606	7,000
	MCD012AA50BA-LH	026-2697	4,500		MCD060D1Z0CA	026-1606	7,000
	MCD012AAP0BA-LH	026-0200	2,500		MCD060DBP0AA-DM	026-2136	7,000
	MCD012AAP0BA-RH	026-0200-001	2,500		MCD060DBP0AA-RH	999-0261606-RH	7,000
	MCD012AAP0CA-LH	026-0200	2,500		MCD060DBP0BA	026-1606	7,000
	MCD012AAP0CA-RH	026-0200-001	2,500			026-2136	7,000
	MCD012AAP0DA-LH	026-2854	2,000		MCD060DBP0CA	026-1606	7,000
	MCD012AAP0DA-RH	026-2863	2,000		MCD060DBZ0AA	026-1606	7,000
MCD012FB00AA-DM	026-1577	2,500		MCD060DBZ0BA	026-1606	7,000	
15,000	MCD015AA00BA	026-0201-001	3,500		MCD060DBZ0CA	026-1606	7,000
18,000	MCD018AA00BA-LH	026-0201	3,500	12,000	MCD512D100BA	026-1577	2,500
	MCD018AA00BA-RH	026-0201-001	3,500		MCD512D100CA	026-1577	2,500
	MCD018AA00CA-LH	026-0201	3,500		MCD512D1E0BA	026-1577	2,500
	MCD018AA00CA-RH	026-0201-001	3,500		MCD512D1E0CA	026-1577	2,500
	MCD018AA00DA-LH	026-2855	3,000		MCD512D1P0BA	026-1577	2,500
	MCD018AA00DA-RH	026-2864	3,000		MCD512D1P0CA	026-1577	2,500
	MCD018AA50BA-LH	026-2711	6,500		MCD512D1S0BA	026-1577	2,500

# COIL REPLACEMENT

## MCD Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
	MCD018AAP0BA-LH	026-0201	3,500		MCD512D1S0CA	026-1577	2,500
	MCD018AAP0BA-RH	026-0201-001	3,500		MCD512DB00AA	026-1577	2,500
	MCD018AAP0CA-LH	026-0201	3,500		MCD512DB00BA	026-1577	2,500
	MCD018AAP0CA-RH	026-0201-001	3,500		MCD512DB00CA	026-1577	2,500
	MCD018AAP0DA-LH	026-2855	3,000		MCD512DBE0BA	026-1577	2,500
	MCD018AAP0DA-RH	026-2864	3,000		MCD512DBE0CA	026-1577	2,500
	MCD018BA00BA	026-0394	3,500		MCD512DBP0BA	026-1577	2,500
	MCD018BAP0BA	026-0394	3,500		MCD512DBP0CA	026-1577	2,500
	MCD018FB00AA-DM	026-1597	4,000		MCD512DBS0BA	026-1577	2,500
24,000	MCD024AA00BA-LH	026-0202	4,000	MCD512DBS0CA	026-1577	2,500	
	MCD024AA00BA-RH	026-0202-001	4,000	18,000	MCD518D100BA	026-1578	2,500
	MCD024AA00CA-LH	026-0202	4,000		MCD518D100CA	026-1578	2,500
	MCD024AA00CA-RH	026-0202-001	4,000		MCD518D1F0BA	026-1578	2,500
	MCD024AA00DA-LH	026-2856	3,500		MCD518D1F0CA	026-1578	2,500
	MCD024AA00DA-RH	026-2865	3,000		MCD518D1P0AA	026-1578	2,500
	MCD024AA50BA-LH	026-2822	6,500		MCD518D1P0BA	026-1578	2,500
	MCD024AAP0BA-LH	026-0202	4,000		MCD518D1P0CA	026-1578	2,500
	MCD024AAP0BA-RH	026-0202-001	4,000		MCD518D1T0BA	026-1578	2,500
	MCD024AAP0CA-LH	026-0202	4,000		MCD518D1T0CA	026-1578	2,500
	MCD024AAP0CA-RH	026-0202-001	4,000		MCD518DB00AA	026-1578	2,500
	MCD024AAP0DA-LH	026-2856	3,500		MCD518DB00BA	026-1578	2,500
	MCD024AAP0DA-RH	026-2865	3,000		MCD518DB00CA	026-1578	2,500
	MCD024BA00BA	026-0301	4,000		MCD518DBF0BA	026-1578	2,500
	MCD024BAP0BA	026-0301	4,000		MCD518DBF0CA	026-1578	2,500
	MCD024FB00AA-DM	026-1597	4,000		MCD518DBP0BA	026-1578	2,500
	30,000	MCD030AA00BA	026-0203		6,500	MCD518DBP0BA-LH	026-1578
MCD030AAP0BA		026-0203	6,500		MCD518DBP0BA-RH	999-0261578-RH	2,500
MCD030BA00BA		026-0302	6,500	MCD518DBP0CA	026-1578	2,500	
MCD030BAP0BA		026-0302	6,500	MCD518DBS0BA	026-1578	2,500	
MCD030DB00AA		026-1597	4,000	MCD518DBT0BA	026-1578	2,500	
MCD030DB00BA		026-1597	4,000	MCD518DBT0CA	026-1578	2,500	
MCD030DB00CA		026-1597	4,000	24,000	MCD524D100AA	026-1579	3,500
MCD030DB0LAA		026-1597	4,000		MCD524D100BA	026-1579	3,500
MCD030DBP0AA		026-1597	4,000		MCD524D100CA	026-1579	3,500
MCD030DBP0BA		026-1597	4,000		MCD524D1G0BA	026-1579	3,500
MCD030DBP0CA		026-1597	4,000		MCD524D1G0CA	026-1579	3,500
MCD030DBPLAA		026-1597	4,000		MCD524D1P0AA	026-1579	3,500
MCD030EB00AA		026-1597	4,000		MCD524D1P0BA	026-1579	3,500
MCD030EB00BA		026-1597	4,000		MCD524D1P0CA	026-1579	3,500
MCD030EB50BA		026-2754	7,000		MCD524D1U0BA	026-1579	3,500
MCD030EBP0AA		026-1597	4,000		MCD524D1U0CA	026-1579	3,500
MCD030EBP0BA		026-1597	4,000		MCD524DB00AA	026-1579	3,500
MCD030FB00AA-DM		026-1581	4,500		MCD524DB00BA	026-1579	3,500
36,000		MCD036AA00BA	026-0204	7,000	MCD524DB00CA	026-1579	3,500
		MCD036AAP0BA	026-0204	7,000	MCD524DBG0BA	026-1579	3,500
	MCD036BA00BA	026-0212	7,000	MCD524DBG0CA	026-1579	3,500	
	MCD036BAP0BA	026-0212	7,000	MCD524DBP0BA	026-1579	3,500	

# COIL REPLACEMENT

## MCD Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price	
	MCD036DB00AA	026-1598	4,500	30,000	MCD524DBP0BA-LH	026-1579	3,500	
	MCD036DB00BA	026-1598	4,500		MCD524DBP0BA-RH	999-0261579-RH	3,500	
	MCD036DB00CA	026-1598	4,500		MCD524DBP0CA	026-1579	3,500	
	MCD036DB0LAA	026-1598	4,500		MCD524DBT0BA	026-1579	3,500	
	MCD036DBP0AA	026-1598	4,500		MCD524DBU0BA	026-1579	3,500	
	MCD036DBP0BA	026-1598	4,500		MCD524DBU0CA	026-1579	3,500	
	MCD036DBP0CA	026-1598	4,500		MCD530D100BA	026-1580	4,000	
	MCD036DBPLAA	026-1598	4,500		MCD530D100CA	026-1580	4,000	
	MCD036EB00AA	026-2129	4,500		MCD530D1H0BA	026-1580	4,000	
	MCD036EB00BA	026-2129	4,500		MCD530D1H0CA	026-1580	4,000	
	MCD036EB50AA	026-2723	7,000		MCD530D1P0BA	026-1580	4,000	
	MCD036EB50BA	026-2857	8,000		MCD530D1P0CA	026-1580	4,000	
	MCD036EBP0AA	026-2129	4,500		MCD530D1V0BA	026-1580	4,000	
	MCD036EBP0BA	026-2129	4,500		MCD530D1V0CA	026-1580	4,000	
	MCD036FB00AA-DM	026-1581	4,500		MCD530DB00BA	026-1580	4,000	
		026-1606	7,000	MCD530DB00CA	026-1580	4,000		
42,000	MCD042EB50AA	026-2728	9,000	MCD530DBH0BA	026-1580	4,000		
48,000	MCD048BA00BA	026-0395	6,000	MCD530DBH0CA	026-1580	4,000		
	MCD048BAP0BA	026-0395	6,000	MCD530DBP0BA	026-1580	4,000		
	MCD048D1P0AA	026-1700	6,000	MCD530DBP0BA-LH	026-1580	4,000		
	MCD048D1P0BA	026-1700	6,000	MCD530DBP0BA-RH	999-0261580-RH	4,000		
	MCD048D1P0CA	026-1700	6,000	MCD530DBP0CA	026-1580	4,000		
	MCD048D1Y0AA	026-1700	6,000	MCD530DBV0BA	026-1580	4,000		
	MCD048D1Y0BA	026-1700	6,000	MCD530DBV0CA	026-1580	4,000		
	MCD048D1Y0CA	026-1700	6,000	36,000	MCD536D100BA	026-1581	4,500	
	MCD048DBP0AA-DM	026-2135	6,000		MCD536D100CA	026-1581	4,500	
	MCD048DBP0AA-RH	999-0261700-RH	6,000		MCD536D1I0BA	026-1581	4,500	
	MCD048DBP0BA	026-1700	6,000		MCD536D1I0CA	026-1581	4,500	
			026-2135		6,000	MCD536D1P0BA	026-1581	4,500
	MCD048DBY0AA	026-1700	6,000		MCD536D1P0CA	026-1581	4,500	
	MCD048DBY0BA	026-1700	6,000		MCD536D1W0BA	026-1581	4,500	
	MCD048DBY0CA	026-1700	6,000		MCD536D1W0CA	026-1581	4,500	
			MCD536DB00BA		026-1581	4,500		
			MCD536DB00CA		026-1581	4,500		
			MCD536DBI0BA		026-1581	4,500		
			MCD536DBI0CA		026-1581	4,500		
			MCD536DBP0BA		026-1581	4,500		
			MCD536DBP0BA-LH		999-0261581LH-P	4,500		
			MCD536DBP0BA-RH		999-0261581RH-P	4,500		
			MCD536DBP0CA	026-1581	4,500			
			MCD536DBW0BA	026-1581	4,500			
			MCD536DBW0CA	026-1581	4,500			

# COIL REPLACEMENT

---

## MCC Series

BTU/H	Model	P/N	Listed Price
18,000	MCC5181B0RAA	026-2480	6,500
	MCC5181B0RAB	026-2480	6,500
24,000	MCC5241B0RAA	026-2480	6,500
	MCC5241B0RAB	026-2480	6,500
30,000	MCC5301B0RAA	026-2481	9,000
	MCC5301B0RAB	026-2481	9,000
36,000	MCC5361B0RAA	026-2533	13,000
	MCC5361B0RAB	026-2533	13,000

## MCV Series

BTU/H	Model	P/N	Listed Price
36,000	MCV036A10WAA	026-0540	7,500
	MCV036AB0WAA	026-0540	7,500
	MCV036B10WAA	026-2848	7,500
	MCV036BB0WAA	026-2848	7,500
48,000	MCV048A10WAA	026-0541	10,000
	MCV048AB0WAA	026-0541	10,000
	MCV048B10WAA	026-2849	10,000
	MCV048BB0WAA	026-2849	10,000
60,000	MCV060A10WAA	026-0542	13,000
	MCV060AB0WAA	026-0542	13,000
	MCV060B10WAA	026-2850	13,000
	MCV060BB0WAA	026-2850	13,000
90,000	MCV090A10WAA	026-0543	16,500
	MCV090AB0WAA	026-0543	16,500
	MCV090BB0WAA	026-2569	16,500
120,000	MCV120AB0WAA	026-2037	20,000
	MCV120BB0WAA	026-2570	22,000



# COIL REPLACEMENT

## TTH/TWE Series

BTU/H	Model	P/N	Listed Price
60,000	TTH060BD00AA	026-1563	12,000
	TTH060BD00BA-DM	026-2944	8,000
	TTH060BD00CA-DM	026-1971	8,000
	TTH060BD0ABA-DM	026-2944	8,000
	TTH060BDA0BA-DM	026-2944	8,000
	TTH060BDB0BA-DM	026-2944	8,000
	TTH060BE00AA	026-1563	12,000
	TTH060BK00AA	026-1563	12,000
	TTH060BK00BA	026-2944	8,000
	TTH060ED00BA	026-2944	8,000
75,000	TTH075BD00AA	026-1564	CALL
	TTH075BD00BA-DM	026-2945	9,000
	TTH075BD00CA-DM	026-2015	CALL
	TTH075BD0AAA-DM	026-1564	17,000
	TTH075BD0ABA-DM	026-2945	9,000
	TTH075BD0ACA-DM	026-2015	CALL
	TTH075BDB0AA-DM	026-1564	17,000
	TTH075BDB0BA-DM	026-2945	9,000
	TTH075BDB0CA-DM	026-2015	CALL
	TTH075BDBAAA-DM	026-1564	17,000
	TTH075BDBABA-DM	026-2945	9,000
	TTH075BDBACA-DM	026-2015	CALL
	TTH075BE00AA	026-1564	17,000
	TTH075BK00A	026-1564	17,000
	TTH075BK00BA	026-2945	9,000
TTH075ED00BA	026-2945	9,000	
100,000	TTH100BD00BA-DM	026-2946	11,000
	TTH100BD00CA-DM	026-2016	12,000
	TTH100BD0AAA-DM	026-1565	17,000
	TTH100BD0ABA-DM	026-2946	11,000
	TTH100BD0ACA-DM	026-2016	12,000
	TTH100BK00A	026-1565	17,000
	TTH100ED00BA	026-2946	11,000

# COIL REPLACEMENT

## TTH/TWE Series

BTU/H	Model	P/N	Listed Price
120,000	TWE120AD00AA-DM	026-1517	20,000
	TWE120AD0AAA-DM	026-1517	20,000
	TWE120AD0BAA-DM	026-1517	20,000
	TWE120AD0CAA-DM	026-1517	20,000
	TWE120ADC0AA-DM	026-1517	20,000
	TWE120ADCAAA-DM	026-1517	20,000
	TWE120ADCBAA-DM	026-1517	20,000
	TWE120ADCCAA-DM	026-1517	20,000
	TWE120AK00AA	026-1517	20,000
	TWE120CD00AA-DM	026-2572	18,000
	TWE120CD0AAA-DM	026-2572	18,000
	TWE120CD0BAA-DM	026-2572	18,000
	TWE120CD0CAA-DM	026-2572	18,000
	TWE120CDC0AA-DM	026-2572	18,000
	TWE120CDCAAA-DM	026-2572	18,000
	TWE120CDCBAA-DM	026-2572	18,000
	TWE120CDCCAA-DM	026-2572	18,000
	TWE120ED00AA	026-2572	18,000
	160,000	TWE160CD00AA-DM	026-2591
TWE160CD0AAA-DM		026-2591	28,000
TWE160CD0BAA-DM		026-2591	28,000
TWE160CD0CAA-DM		026-2591	28,000
TWE160CDC0AA-DM		026-2591	28,000
TWE160CDCAAA-DM		026-2591	28,000
TWE160CDCBAA-DM		026-2591	28,000
TWE160CDCCAA-DM		026-2591	28,000
TWE160ED00AA	026-2591	28,000	
180,000	TWE180BD00AA-DM	026-1527	37,000
	TWE180BD0AAA-DM	026-1527	37,000
	TWE180BD0BAA-DM	026-1527	37,000
	TWE180BD0CAA-DM	026-1527	37,000
	TWE180BDD0AA-DM	026-1527	37,000
	TWE180BDDAAA-DM	026-1527	37,000
	TWE180BDDBAA-DM	026-1527	37,000
	TWE180BDDCAA-DM	026-1527	37,000
	TWE180BK00AA	026-1527	37,000
	TWE180CD00AA-DM	026-2581	28,000
	TWE180CD0AAA-DM	026-2581	28,000
	TWE180CD0BAA-DM	026-2581	28,000
	TWE180CD0CAA-DM	026-2581	28,000
	TWE180CDD0AA-DM	026-2581	28,000
	TWE180CDDAAA-DM	026-2581	28,000
	TWE180CDDBAA-DM	026-2581	28,000
	TWE180CDDCAA-DM	026-2581	28,000
	TWE180ED00AA	026-2581	28,000

# COIL REPLACEMENT

BTU/H	Model	P/N	Listed Price
210,000	TWE210CD00AA-DM	026-2594	32,000
	TWE210CD0AAA-DM	026-2594	32,000
	TWE210CD0BAA-DM	026-2594	32,000
	TWE210CD0CAA-DM	026-2594	32,000
	TWE210CDD0AA-DM	026-2594	32,000
	TWE210CDDAAA-DM	026-2594	32,000
	TWE210CDDBAA-DM	026-2594	32,000
	TWE210CDDCAA-DM	026-2594	32,000
	TWE210ED00AA	026-2594	32,000
240,000	TWE240BD00AA-DM	026-1528	38,000
	TWE240BD0AAA-DM	026-1528	38,000
	TWE240BD0BAA-DM	026-1528	38,000
	TWE240BD0CAA-DM	026-1528	38,000
	TWE240BD0EAA-DM	026-1528	38,000
	TWE240BDEAAA-DM	026-1528	38,000
	TWE240BDEBAA-DM	026-1528	38,000
	TWE240BDECAA-DM	026-1528	38,000
	TWE240BK00AA	026-1528	38,000
	TWE240CD00AA-DM	026-2615	36,000
	TWE240CD0AAA-DM	026-2615	36,000
	TWE240CD0BAA-DM	026-2615	36,000
	TWE240CD0CAA-DM	026-2615	36,000
	TWE240CDE0AA-DM	026-2615	36,000
	TWE240CDEAAA-DM	026-2615	36,000
	TWE240CDEBAA-DM	026-2615	36,000
	TWE240CDECAA-DM	026-2615	36,000
	TWE240ED00AA	026-2615	36,000

# COIL REPLACEMENT

## TTV Series

BTU/H	Model	P/N	Listed Price
250,000	TTV250AD01A0AA0D	026-2147	36,000
	TTV250AD01A0AB0D-DM-ARR2	026-2147	36,000
	TTV250AD01A0AC0D-ARR.3 OP	026-2147	36,000
	TTV250AD01A0AD0D-ARR.4-OP	026-2147	36,000
	TTV250AD01A0BA0D	026-2147	36,000
	TTV250AD01A0BC0D	026-2147	36,000
	TTV250AD01A0BD0D	026-2147	36,000
	TTV250AD02A0AA0D	026-2147	36,000
	TTV250AD11A0AA0D-ARR1	026-2147	36,000
	TTV250AD11A0AB0D-ARR2	026-2147	36,000
	TTV250AD11A0AC0D-ARR.3	026-2147	36,000
	TTV250AD11A0AD0D-ARR.4-OP	026-2147	36,000
	TTV250AD11A0BA0D	026-2147	36,000
	TTV250AD11A0BC0D	026-2147	36,000
	TTV250AD11A0BD0D	026-2147	36,000
	TTV250AD12A0AA0D	026-2147	36,000
300,000	TTV300A402A0AA0D	026-2149	38,000
	TTV300AD02A0AA0D	026-2149	38,000
	TTV300AD02A0AB0D-DM-ARR2	026-2149	38,000
	TTV300AD02A0AC0D	026-2149	38,000
	TTV300AD02A0AD0D-ARR.4-OP	026-2149	38,000
	TTV300AD02A1CA0D	026-2149	38,000
	TTV300AD03A0AA0D	026-2149	38,000
	TTV300AD03A0AC0D	026-2149	38,000
	TTV300AD03A0BA0D	026-2149	38,000
	TTV300AD12A0AA0D	026-2149	38,000
	TTV300AD12A0AB0D-ARR2	026-2149	38,000
	TTV300AD12A0AC0D-ARR.3-OP	026-2149	38,000
	TTV300AD12A0AD0D-ARR.4-OP	026-2149	38,000
	TTV300AD12A1CA0D	026-2149	38,000
	TTV300AD13A0AA0D	026-2149	38,000
	TTV300AD13A0AC0D	026-2149	38,000
TTV300AD14A1AA0D	026-2149	38,000	
TTV300AK02A0AA0D	026-2149	38,000	
400,000	TTV400AD02A0AA0D	026-2151	53,000
	TTV400AD02A0AB0D-DM-ARR2	026-2151	53,000
	TTV400AD02A0AC0D-ARR.3-OP	026-2151	53,000
	TTV400AD02A0AD0D-ARR.4-OP	026-2151	53,000
	TTV400AD02A1AA0D	026-2151	53,000
	TTV400AD02A1AB0D	026-2151	53,000
	TTV400AD02A1AC0D	026-2151	53,000
	TTV400AD02A1AD0D	026-2151	53,000
	TTV400AD03A0AA0D	026-2151	53,000
	TTV400AD03A0AB0D-DM-ARR2	026-2151	53,000
	TTV400AD03A0BA0D	026-2151	53,000
	TTV400AD03A1AB0D	026-2151	53,000
	TTV400AD12A0AA0D-ARR1	026-2151	53,000
	TTV400AD12A0AB0D-ARR2	026-2151	53,000

# COIL REPLACEMENT

## TTV Series

BTU/H	Model	P/N	Listed Price
	TTV400AD12A0AC0D-ARR.3-OP	026-2151	53,000
	TTV400AD12A0AD0D-ARR.4-OP	026-2151	53,000
	TTV400AD12A1AA0D	026-2151	53,000
	TTV400AD12A1AB0D	026-2151	53,000
	TTV400AD12A1AC0D	026-2151	53,000
	TTV400AD12A1AD0D	026-2151	53,000
	TTV400AD13A0AA0D	026-2151	53,000
	TTV400AD13A0AB0D-ARR2	026-2151	53,000
	TTV400AD13A1AA0D	026-2151	53,000
	TTV400AD13A1AB0D	026-2151	53,000
500,000	TTV500AD03A0AA0D	026-2153	52,000
		026-2154	52,000
	TTV500AD03A0AB0D-DM-ARR2	026-2153	52,000
		026-2154	52,000
	TTV500AD03A0AC0D-ARR.3-OP	026-2153	52,000
		026-2154	52,000
	TTV500AD03A0AD0D-ARR.4-OP	026-2153	52,000
		026-2154	52,000
	TTV500AD03A1AA0D	026-2153	52,000
		026-2154	52,000
	TTV500AD03A1AB0D	026-2153	52,000
		026-2154	52,000
	TTV500AD03A1AC0D	026-2153	52,000
		026-2154	52,000
	TTV500AD03A1AD0D	026-2153	52,000
		026-2154	52,000
	TTV500AD04A0AC0D	026-2153	52,000
		026-2154	52,000
	TTV500AD13A0AA0D-ARR1	026-2153	52,000
		026-2154	52,000
	TTV500AD13A0AB0D-ARR2	026-2153	52,000
		026-2154	52,000
	TTV500AD13A0AC0D-ARR.3-OP	026-2153	52,000
		026-2154	52,000
	TTV500AD13A0AD0D-ARR.4-OP	026-2153	52,000
		026-2154	52,000
	TTV500AD13A1AA0D	026-2153	52,000
		026-2154	52,000
	TTV500AD13A1AB0D	026-2153	52,000
		026-2154	52,000
TTV500AD13A1AC0D	026-2153	52,000	
	026-2154	52,000	
TTV500AD13A1AD0D	026-2153	52,000	
	026-2154	52,000	
TTV500AD14A0AB0D	026-2153	52,000	
	026-2154	52,000	
TTV600AD04A0AA0D	026-2155	56,000	
	026-2156	56,000	



# COIL REPLACEMENT

## TTV Series

BTU/H	Model	P/N	Listed Price
600,000	TTV600AD04A0AB0D-DM-ARR2	026-2155	56,000
		026-2156	56,000
	TTV600AD04A0AC0D-ARR.3-OP	026-2155	56,000
		026-2156	56,000
	TTV600AD04A0AD0D-ARR.4-OP	026-2155	56,000
		026-2156	56,000
	TTV600AD04A1AA0D	026-2155	56,000
		026-2156	56,000
	TTV600AD04A1AB0D	026-2155	56,000
		026-2156	56,000
	TTV600AD04A1AC0D	026-2155	56,000
		026-2156	56,000
	TTV600AD04A1AD0D	026-2155	56,000
		026-2156	56,000
	TTV600AD05A0AB0D	026-2155	56,000
		026-2156	56,000
	TTV600AD05A1AB0D	026-2155	56,000
		026-2156	56,000
	TTV600AD14A0AA0D-ARR1	026-2155	56,000
		026-2156	56,000
	TTV600AD14A0AB0D-ARR2	026-2155	56,000
		026-2156	56,000
	TTV600AD14A0AC0D-ARR.3-OP	026-2155	56,000
		026-2156	56,000
	TTV600AD14A0AD0D	026-2155	56,000
		026-2156	56,000
	TTV600AD14A1AA0D	026-2155	56,000
		026-2156	56,000
	TTV600AD14A1AB0D	026-2155	56,000
		026-2156	56,000
	TTV600AD14A1AC0D	026-2155	56,000
		026-2156	56,000
TTV600AD14A1AD0D	026-2155	56,000	
	026-2156	56,000	
TTV600AD15A0AB0D	026-2155	56,000	
	026-2156	56,000	
TTV600AD15A1AB0D	026-2155	56,000	
	026-2156	56,000	

# COIL REPLACEMENT

## TTK Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price	
12,000	TTK012QB00AA	026-0652-003	2,500	9,000	TTK509LB50BA	026-0652-003	2,500	
	TTK012QB00AA-A	026-0652-003	2,500		TTK509M100DB	026-0652-002	2,500	
	TTK012QB00AA-B	026-0652-003	2,500		TTK509M1HEBG	026-0652-003	2,500	
	TTK012QB00AA-C	026-0652-003	2,500		TTK509MA0EBG	026-0652-002	2,500	
	TTK012QB00AA-D	026-0652-003	2,500		TTK509P10EDA	026-1808	2,500	
	TTK012QB00AA-E	026-0652-003	2,500		TTK509PB0EFA	026-1808	2,500	
	TTK012QB00AA-F	026-0652-003	2,500		TTK509PB0EGA-DM	026-1808	2,500	
	TTK012QB00BA	026-0652-003	2,500		TTK509PB50AA	026-2138	3,500	
	TTK012QB00BA-A	026-0652-003	2,500		TTK509PB5EDA	026-2138	3,500	
	TTK012QB00BA-B	026-0652-003	2,500		TTK509PB5EGA-DM	026-2138	3,500	
	TTK012QB00BA-C	026-0652-003	2,500		TTK509PBHEFA	026-1809	3,500	
	TTK012QB00BA-D	026-0652-003	2,500		12,000	TTK512JA00AA	026-0652-003	2,500
	TTK012QB00BA-E	026-0652-003	2,500			TTK512L100CB	026-0652-003	2,500
TTK012QB00BA-F	026-0652-003	2,500	TTK512LB00BA	026-0652-003		2,500		
15,000	TTK015QB00AA	026-0580-003	3,000	TTK512LB00BB		026-0652-003	2,500	
	TTK015QB00AA-A	026-0580-003	3,000	TTK512LB00CA		026-0652-003	2,500	
	TTK015QB00AA-B	026-0580-003	3,000	TTK512LB00DA		026-0580-003	3,000	
	TTK015QB00AA-C	026-0580-003	3,000	TTK512LB50BB		026-0508-004	4,500	
	TTK015QB00AA-D	026-0580-003	3,000	TTK512LB50CB		026-2619	4,500	
	TTK015QB00AA-E	026-0580-003	3,000	TTK512LB50DA		026-2619	4,500	
	TTK015QB00AA-F	026-0580-003	3,000	TTK512M1HEBG		026-0652-003	2,500	
	TTK015QB00BA	026-0508-004	4,500	TTK512MA0EBG		026-0652-003	2,500	
	TTK015QB00BA-A	026-0508-004	4,500	TTK512MB5ECG-DM		026-0652-003	2,500	
	TTK015QB00BA-B	026-0508-004	4,500	TTK512MB5EDG		026-2504	4,500	
	TTK015QB00BA-C	026-0508-004	4,500	TTK512MB5EFG	026-0508-004	4,500		
	TTK015QB00BA-D	026-0508-004	4,500	TTK512P100FA	026-1809	3,500		
	TTK015QB00BA-E	026-0508-004	4,500	TTK512P100GA	026-2642	4,100		
TTK015QB00BA-F	026-0508-004	4,500	TTK512PB00FA-DM	026-1809	3,500			
18,000	TTK018QB00AA	026-0508-004	4,500	TTK512PB00HA	026-2642	4,100		
	TTK018QB00AA-A	026-0508-004	4,500	TTK512PB00JA	026-2642	4,100		
	TTK018QB00AA-B	026-0508-004	4,500	TTK512PB0EFA	026-1809	3,500		
	TTK018QB00AA-C	026-0508-004	4,500	TTK512PB0EGA-DM	026-1809	3,500		
	TTK018QB00AA-D	026-0508-004	4,500	TTK512PB0EHA-DM	026-2642	4,100		
	TTK018QB00AA-E	026-0508-004	4,500	TTK512PBHEFA	026-1798	5,000		
	TTK018QB00AA-F	026-0508-004	4,500	TTK512QB00AA	026-0652-003	2,500		
	TTK018QB00BA	026-1798	5,000	15,000	TTK515JA00AA	026-0580-003	3,000	
	TTK018QB00BA-A	026-1798	5,000		TTK515LB00BA	026-0580-003	3,000	
	TTK018QB00BA-C	026-1798	5,000		TTK515LB00CA	026-0508-004	4,500	
	TTK018QB00CA	026-2622	5,000		TTK515QB00AA	026-0508-004	4,500	
	TTK018QB00CA-A	026-2622	5,000		18,000	TTK518L100CB	026-0508-004	4,500
	TTK018QB00CA-B	026-2622	5,000			TTK518L100DA	026-0508-004	4,500
TTK018QB00CA-C	026-2622	5,000	TTK518LB00BA			026-0508-004	4,500	
TTK018QB00CA-D	026-2622	5,000	TTK518LB00BB			026-0508-004	4,500	
TTK018QB00CA-E	026-2622	5,000	TTK518LB00CA			026-2619	4,500	
TTK018QB00CA-F	026-2622	5,000	TTK518LB00DA			026-2622	5,000	
24,000	TTK024QB00AA	026-0509-004	6,000			TTK518LB50BA	026-0509-004	6,000
	TTK024QB00AA-A	026-0509-004	6,000			TTK518LB50CA	026-2507	6,000

# COIL REPLACEMENT

## TTK Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
	TTK024QB00AA-B	026-0509-004	6,000		TTK518LB50CA-DM	026-0509-006	6,000
	TTK024QB00AA-C	026-0509-004	6,000		TTK518LB50FA	026-2507	6,000
	TTK024QB00AA-D	026-0509-004	6,000		TTK518LB50GA	026-2507	6,000
	TTK024QB00AA-E	026-0509-004	6,000		TTK518MA0EBG	026-0508-004	4,500
	TTK024QB00AA-F	026-0509-004	6,000		TTK518MB5ECG-DM	026-1799	7,500
	TTK024QB00BA	026-1798	5,000		TTK518MB5EDG	026-2507	6,000
	TTK024QB00BA-A	026-1798	5,000		TTK518P100GA	026-1798	5,000
	TTK024QB00BA-C	026-1798	5,000		TTK518P10EFA	026-1799	7,500
	TTK024QB00BA-DM	026-1798	5,000		TTK518PB00FA	026-1798	5,000
	TTK024QB00CA	026-0509-006	6,000		TTK518PB00FA-DM	026-1798	5,000
	TTK024QB00CA-A	026-0509-006	6,000		TTK518PB00GA	026-1798	5,000
	TTK024QB00CA-B	026-0509-006	6,000		TTK518PB0EGA-DM	026-1798	5,000
	TTK024QB00CA-C	026-0509-006	6,000		TTK518PBHEFA	026-1798	5,000
	TTK024QB00CA-D	026-0509-006	6,000		TTK518QB00AA	026-2622	5,000
	TTK024QB00CA-E	026-0509-006	6,000		TTK521JA00AA	026-0508-004	4,500
	TTK024QB00CA-F	026-0509-006	6,000		TTK524KB100AA	026-1799	7,500
	30,000	TTK030QB00BA	026-0645-004		7,500	21,000	TTK524L100CB
TTK030QB00BA-A		026-0645-004	7,500	24,000	TTK524LB00BA	026-0509-004	6,000
TTK030QB00BA-B		026-0645-004	7,500	TTK524LB00CB	026-0509-004	6,000	
TTK030QB00BA-C		026-0645-004	7,500	TTK524LB00EA	026-0509-004	6,000	
TTK030QB00BA-D		026-0645-004	7,500	TTK524LB00FA	026-2622	5,000	
TTK030QB00BA-F		026-0645-004	7,500	TTK524LB00GA	026-0509-006	6,000	
TTK030QB00CA		026-1799	7,500	TTK524LB00HA	026-0509-006	6,000	
TTK030QB00CA-A		026-1799	7,500	TTK524LB50BA	026-0645-004	7,500	
TTK030QB00CA-C		026-1799	7,500	TTK524LB50CA	026-0646-006	12,000	
TTK030QB00DA		026-1799	7,500	TTK524LB50DA	026-0646-006	12,000	
TTK030QB00EA		026-1799	7,500	TTK524LB50GA	026-2753	9,000	
TTK030QB00EA-A		026-1799	7,500	TTK524LB50HA	026-2753	9,000	
TTK030QB00EA-B		026-1799	7,500	TTK524MA0EBG	026-0509-004	6,000	
TTK030QB00EA-C		026-1799	7,500	TTK524MB0ECG-DM	026-1799	7,500	
TTK030QB00EA-D		026-1799	7,500	TTK524MB0EDG	026-2507	6,000	
TTK030QB00EA-E		026-1799	7,500	TTK524MB0EEA	026-2507	6,000	
TTK030QB00EA-F		026-1799	7,500	TTK524MB0EFA	026-2507	6,000	
TTK030QB00EA-G		026-1799	7,500	TTK524MB0EGA	026-2507	6,000	
TTK030QB00FA		026-1799	7,500	TTK524MB5EAA	026-2753	9,000	
TTK030QD00AA		026-1799	7,500	TTK524P100GA	026-1798	5,000	
TTK030QD00CA-B		026-1730	8,500	TTK524PB00HA	026-2507	6,000	
TTK030QD00CA-D		026-1730	8,500	TTK524PB0EFA	026-1798	5,000	
TTK030QD00CA-F		026-1730	8,500	TTK524PB0EGA-DM	026-1798	5,000	
36,000	TTK036KD00AA	026-0469-004	12,000	TTK524PB50GA-DM	026-1799	7,500	
	TTK036QB00BA	026-0646-004	12,000	TTK524QB00AA	026-0509-006	6,000	
	TTK036QB00BA-A	026-0646-004	12,000	TTK524QB00BA	026-0509-006	6,000	
	TTK036QB00BA-B	026-0646-004	12,000	25,000	TTK525JA00AA	026-0509-004	6,000
	TTK036QB00BA-C	026-0646-004	12,000	30,000	TTK530JA00AA	026-0645-004	7,500
	TTK036QB00BA-D	026-0646-004	12,000	TTK530K100CB	026-0645-004	7,500	
	TTK036QB00BA-F	026-0646-004	12,000	TTK530KB00BB-DM	026-0645-004	7,500	
	TTK036QB00CA	026-1730	8,500	TTK530KB00EA	026-0645-004	7,500	

# COIL REPLACEMENT

## TTK Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price
	TTK036QB00CA-A	026-1730	8,500		TTK530KB00FA	026-1799	7,500
	TTK036QB00CA-B	026-1730	8,500		TTK530KB00GA	026-0645-004	7,500
	TTK036QB00CA-C	026-1730	8,500		TTK530KB00HA	026-0646-006	12,000
	TTK036QB00CA-D	026-1730	8,500		TTK530KB100AA	026-0646-004	12,000
	TTK036QB00CA-E	026-1730	8,500		TTK530KB50BA	026-0646-004	12,000
	TTK036QB00CA-F	026-1730	8,500		TTK530KB50CA	026-0646-006	12,000
	TTK036QB00CA-G	026-1730	8,500		TTK530KB50DA	026-2753	9,000
	TTK036QB00EA-DM	026-1730	8,500		TTK530KB50FA	026-2753	9,000
	TTK036QD00AA	026-0646-004	12,000		TTK530KBS0AA	026-2507	6,000
	TTK036QD00AA-A	026-0646-004	12,000		TTK530KBS0BA	026-2507	6,000
	TTK036QD00AA-B	026-0646-004	12,000		TTK530KD00BA	026-0645-004	7,500
	TTK036QD00AA-C	026-0646-004	12,000		TTK530KD00CA-DM	026-0645-004	7,500
	TTK036QD00AA-F	026-0646-004	12,000		TTK530KD00DA	026-2507	6,000
	TTK036QD00BA	026-1730	8,500		TTK530MB0EBG-DM	026-0645-004	7,500
	TTK036QD00BA-D	026-0646-004	12,000		TTK530MB0ECA	026-0645-004	7,500
	TTK036QD00CA	026-1730	8,500		TTK530MB0EDA-DM	026-2507	6,000
	TTK036QD00CA-A	026-1730	8,500		TTK530MB0EFA	026-2507	6,000
	TTK036QD00CA-C	026-1730	8,500		TTK530MB5EAA	026-0646-006	12,000
	TTK036QD00CA-E	026-1730	8,500		TTK530PB00FA-DM	026-1799	7,500
	TTK036QD00CA-G	026-1730	8,500		TTK530QB00AA	026-1799	7,500
	TTK036QD00DA-DM	026-1730	8,500		TTK530QB00BA-DM	026-1799	7,500
42,000	TTK042K100AA	026-1730	8,500	36,000	TTK536JA00AA	026-0646-004	12,000
	TTK042K400BA	026-1730	8,500		TTK536JD00AA	026-0646-004	12,000
	TTK042KD00AA	026-1730	8,500		TTK536K100DA	026-0646-004	12,000
	TTK042KD00CA	026-1730	8,500		TTK536K100EA	026-0646-006	12,000
	TTK042KD50AA	026-0468-003	14,000		TTK536K300AA	026-0646-004	12,000
	TTK042KD50BA	026-2624	14,500		TTK536K300BA	026-0646-006	12,000
	TTK042KD50CA	026-2943	12,500		TTK536K400DA	026-0646-004	12,000
	TTK042KDS0AA	026-1730	8,500		TTK536K400EA	026-0646-006	12,000
	TTK042KDS0BA	026-1730	8,500		TTK536KB00BB	026-0646-004	12,000
	TTK042KDS0CA	026-1730	8,500		TTK536KB00EA	026-0646-004	12,000
	TTK042QB00AA	026-1730	8,500		TTK536KB00FA	026-0646-004	12,000
	TTK042QD00AA	026-1730	8,500		TTK536KB00GA	026-0646-006	12,000
	TTK042QD00AA-A	026-1730	8,500		TTK536KB100AA	026-1730	8,500
	TTK042QD00AA-B	026-1730	8,500		TTK536KB50BA-DM	026-1618	8,500
	TTK042QD00AA-C	026-1730	8,500		TTK536KB50CA	026-2624	14,500
	TTK042QD00AA-D	026-1730-001	8,500		TTK536KB50DA	026-2821	12,000
	TTK042QD00AA-E	026-1730	8,500		TTK536KBS0AA	026-0646-006	12,000
	TTK042QD00AA-F	026-1730	8,500		TTK536KBS0BA	026-2753	9,000
	TTK042QD00BA	026-1730	8,500		TTK536KD00BA	026-0646-004	12,000
	TTK042QD00CA	026-1730	8,500		TTK536KD00BB	026-0646-004	12,000
	TTK042QD00DA	026-1730	8,500		TTK536KD00FA	026-0646-004	12,000
48,000	TTK048K100AA	026-0469-004	12,000		TTK536KD00GA-DM	026-0646-006	12,000
	TTK048K100EA	026-0469-004	12,000		TTK536KD50AA	026-0468-003	14,000
	TTK048K400EA	026-0469-004	12,000		TTK536KD50BA	026-2624	14,500
	TTK048KD00CA	026-0469-004	12,000		TTK536KD50CA	026-2821	12,000
	TTK048KD00CB	026-0469-004	12,000		TTK536KDS0AA	026-0646-006	12,000

# COIL REPLACEMENT

## TTK Series

BTU/H	Model	P/N	Listed Price	BTU/H	Model	P/N	Listed Price	
	TTK048KD00DA	026-0469-004	12,000		TTK536KDS0BA	026-2753	9,000	
	TTK048KD00EA	026-0469-004	12,000		TTK536KH00AA	026-0646-004	12,000	
	TTK048KDS0AA	026-0469-004	12,000		TTK536MB0EAA	026-0646-006	12,000	
	TTK048KDS0BA	026-0469-004	12,000		TTK536MD0EAA	026-0646-006	12,000	
	TTK048KDS0CA	026-0469-004	12,000		TTK536QB00AA	026-1730	8,500	
	TTK048KDS0DA	026-2821	12,000		TTK536QB00BA-DM	026-1730	8,500	
	TTK048QD00AA	026-0469-004	12,000		TTK536QB00CA	026-2753	9,000	
	TTK048QD00AA-B	026-0469-004	12,000		TTK536QD00AA	026-1730	8,500	
	TTK048QD00AA-C	026-0469-004	12,000		TTK536QD00BA-DM	026-1730	8,500	
	TTK048QD00AA-F	026-0469-004	12,000		TTK536QD00CA	026-2753	9,000	
	TTK048QD00BA	026-0469-004	12,000		48,000	TTK548AD00BA	026-0469-004	12,000
	TTK048QD00CA	026-0469-004	12,000		60,000	TTK560AD00BA	026-0468-003	14,000
	TTK048QD00DA	026-0469-004	12,000		OTHERS	TTK709MA0EBG	026-0652-002	2,500
	TTK048QD00EA	026-2821	12,000			TTK709PB0EFA	026-1809	3,500
	60,000	TTK060K100AA	026-0468-003			14,000	TTK709PB5EFA	026-1809
	TTK060K100EA	026-0468-003	14,000	TTK709PB5EHA		026-1809	3,500	
	TTK060K300AA	026-0468-003	14,000	TTK710MA5EBG		026-0580-003	3,000	
	TTK060K400EA	026-0468-003	14,000	TTK712MA0EBG		026-0652-003	2,500	
	TTK060KD00CA	026-0468-003	14,000	TTK712MA5EBG		026-0508-004	4,500	
	TTK060KD00CB	026-0468-003	14,000	TTK712PB0EFA		026-1809	3,500	
	TTK060KD00DA	026-0468-003	14,000	TTK718MA0EBG		026-0508-004	4,500	
	TTK060KD00EA	026-0468-003	14,000	TTK718MA5EBG		026-0509-004	6,000	
	TTK060KDS0AA	026-0468-003	14,000	TTK724MA0EBG		026-0509-004	6,000	
	TTK060KDS0BA	026-0468-003	14,000					
	TTK060KDS0CA	026-2943	12,500					
	TTK060QD00AA	026-0468-003	14,000					
	TTK060QD00AA-B	026-0468-003	14,000					
	TTK060QD00AA-C	026-0468-003	14,000					
	TTK060QD00AA-F	026-0468-003	14,000					
	TTK060QD00BA	026-0468-003	14,000					
	TTK060QD00CA	026-0468-003	14,000					
	TTK060QD00DA	026-0468-003	14,000					
	TTK060QD00EA	026-2943	12,500					



# COIL REPLACEMENT

## TTA Series

BTU/H	Model	P/N	Listed Price
75,000	TTA075DD00BB	026-1567	15,000
	TTA075DD00BD	026-1567	15,000
	TTA075DK00BB	026-1567	15,000
	TTA075ED00QA	026-1837	15,000
	TTA075RD00MA	026-1837	15,000
	TTA075RD00PA	026-1837	15,000
	TTA075RD00QA	026-1837	15,000
	TTA075RDB0PA	026-1837	15,000
	TTA075RDB0QA-DM	026-1837	15,000
100,000	TTA100DD00BB	026-1568	CALL
	TTA100DD00BD	026-1568	CALL
	TTA100DK00BB	026-1568	CALL
	TTA100ED00QA	026-2876	18,000
	TTA100RD00MA	026-1838	19,000
	TTA100RD00PA	026-1838	19,000
	TTA100RD00QA	026-2876	18,000
	TTA100RD0FQA	026-3003	19,000
	TTA100RDB0PA	026-1838	19,000
	TTA100RDB0QA-DM	026-2876	18,000
120,000	TTA120DD00BB	026-1569	CALL
	TTA120DD00BD	026-1569	CALL
	TTA120DK00BB	026-1568	CALL
	TTA120ED00QA	026-2877	23,000
	TTA120RD00MA	026-1839	22,000
	TTA120RD00PA-DM	026-1839	22,000
	TTA120RD00QA	026-2877	23,000
	TTA120RDB0PA	026-1839	22,000
	TTA120RDB0QA-DM	026-2877	23,000
150,000	TTA150ED00BB	026-1567	15,000
		026-1567-001	15,000
	TTA150ED00BD	026-1567	15,000
		026-1567-001	15,000
	TTA150ED00QA	026-1837-001	14,000
	TTA150ED0GQA	026-1837-001	14,000
	TTA150EK00BB	026-1567	15,000
		026-1567-001	15,000
	TTA150RD00MA	026-1837-001	14,000
	TTA150RD00PA	026-1837-001	14,000
	TTA150RD00QA	026-1837-001	14,000
	TTA150RD0GMA-DM	026-1837-001	14,000
	TTA150RD0GPA	026-1837-001	14,000
TTA150RD0GQA	026-1837-001	14,000	

# COIL REPLACEMENT

## TTA Series

BTU/H	Model	P/N	Listed Price	
180,000	TTA180ED00BB	026-1568 026-1568-001	CALL CALL	
	TTA180ED00BD	026-1568 026-1568-001	CALL CALL	
	TTA180ED00QA	026-2879	17,000	
	TTA180ED0GQA	026-2879	17,000	
	TTA180EK00BB	026-1568 026-1568-001	CALL CALL	
	TTA180RD00PA-DM	026-1838-001	20,000	
	TTA180RD00QA	026-2879	17,000	
	TTA180RD0GMA-DM	026-1838-001	20,000	
	TTA180RD0GPA	026-1838-001	20,000	
	TTA180RD0GQA	026-2879	17,000	
	200,000	TTA200ED00BB	026-1568 026-1568-001	CALL CALL
		TTA200ED00BD	026-1568 026-1568-001	CALL CALL
TTA200ED00QA		026-2880	18,000	
TTA200ED0GQA		026-2880	18,000	
TTA200EK00BB		026-1568 026-1568-001	CALL CALL	
TTA200RD00MA		026-1838-001	20,000	
TTA200RD00PA		026-1838-001	20,000	
TTA200RD00QA		026-2880	18,000	
TTA200RD0GMA-DM		026-1838-001	20,000	
TTA200RD0GPA		026-1838-001	20,000	
TTA200RD0GQA		026-2880	18,000	
240,000		TTA240ED00BB	026-1569 026-1569-001	CALL CALL
	TTA240ED00BD	026-1569 026-1569-001	CALL CALL	
	TTA240ED00QA	026-1840	22,000	
	TTA240ED0GQA	026-1840	22,000	
	TTA240EK00BB	026-1568 026-1568-001	CALL CALL	
	TTA240RD00MA	026-1840	22,000	
	TTA240RD00PA	026-1840	22,000	
	TTA240RD00QA	026-1840	22,000	
	TTA240RD0GMA-DM	026-1840	22,000	
	TTA240RD0GPA	026-1840	22,000	
	TTA240RD0GQA	026-1840	22,000	

# COIL REPLACEMENT

---

## RAUP Series

	Model	P/N	Listed Price
	RAUP250D1B0A	026-2142	47,000
	RAUP300D1B0A	026-2143	56,000
	RAUP400D1B0A	026-2144	35,000
	RAUP500D1B0A	026-2145	46,000
	RAUP600D1B0A	026-2146	47,000

## CGAT Series

	Model	P/N	Listed Price
	CGAT065D0000AA	026-1837	15,000
	CGAT065D0000BA	026-1837	15,000
	CGAT065D1000BA	026-1837	15,000
	CGAT085D0000AA	026-1838	19,000
	CGAT085D0000BA	026-1838	19,000
	CGAT085D1000BA	026-1838	19,000
	CGAT105D0000AA	026-1839	22,000
	CGAT105D0000BA	026-1839	22,000
	CGAT105D1000BA	026-1839	22,000
	CGAT135D0000AA	026-1837-001	14,000
	CGAT135D0000BA	026-1837-001	14,000
	CGAT135D1000BA	026-1837-001	14,000
	CGAT175D0000AA	026-1838-001	20,000
	CGAT175D0000BA	026-1838-001	20,000
	CGAT175D1000BA	026-1838-001	20,000
	CGAT215D0000AA	026-1840	22,000
	CGAT215D0000BA	026-1840	22,000
	CGAT215D1000BA	026-1840	22,000